

Received by Chief Ship Surveyor 5.7.15, Received from Chief Ship Surveyor

VESSEL'S NAME *Jm. S. D. Settin'* Rpt. *Lk.* No. 14760

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

*4<sup>th</sup>* S.S. No. 3.

THICKNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in  $\frac{1}{16}$  of an inch.

STRAKE.	AMIDSHIP.					FORWARD.					AFT.					REMARKS.	
	Original Thick- ness.	Thickness by drilling.		Diminution if any.	Original Thick- ness.	Thickness by drilling.		Diminution if any.	Original Thick- ness.	Thickness by drilling.		Diminution if any.	Original Thick- ness.	Thickness by drilling.			
		Port.	Star.			Port.	Star.			Port.	Star.			Port.	Star.		
	In.	In.	In.	In.	In.	In.	In.	In.	In.	In.	In.	In.	In.	In.	In.	In.	
SPAR SHEER STRAKE .....																	
Strake below .....																	
MAIN SHEER STRAKE .....	<i>DOUBLED</i>	<i>8</i>	<i>9</i>	<i>9</i>	<i>· ·</i>	<i>8</i>	<i>9</i>	<i>8</i>	<i>· ·</i>	<i>8</i>	<i>9</i>	<i>8</i>	<i>· ·</i>				
1st Strake below .....	<i>8</i>	<i>8</i>	<i>7f</i>	<i>14</i>	<i>7</i>	<i>8</i>	<i>8</i>	<i>· ·</i>	<i>7</i>	<i>6f</i>	<i>7</i>	<i>14</i>	<i>· ·</i>				
2nd .....	<i>8</i>	<i>9</i>	<i>8f</i>	<i>· ·</i>	<i>7</i>	<i>8</i>	<i>7f</i>	<i>14</i>	<i>7</i>	<i>7</i>	<i>6f</i>	<i>14</i>	<i>· ·</i>	<i>b. bare</i>			
3rd .....	<i>9</i>	<i>9</i>	<i>9</i>	<i>· ·</i>	<i>8</i>	<i>8</i>	<i>8</i>	<i>· ·</i>	<i>8</i>	<i>8</i>	<i>7f</i>	<i>16</i>	<i>· ·</i>				
4th .....					<i>8</i>	<i>9</i>	<i>9</i>	<i>· ·</i>	<i>8</i>	<i>7f</i>	<i>9</i>	<i>14</i>	<i>· ·</i>	<i>p. full</i>			
5th .....																	
6th .....																	
7th .....																	
8th .....																	
9th .....																	

The 4th S.S. No. 3 due 4.14 has now been partly held.

The plating has been drilled with the results shown above which may be considered satisfactory.

The vessel has been examined on the part and the following repairs effected due to wear and tear:-

Frames and reverse frames renewed as necessary, one tank top plate renewed and 6 doubled, bunkers repaired and a number of deck planks renewed and minor repairs effected.

*of proper*  
165 fathoms of cable *the proposed size, weight and test supplied to*  
*Rule*  
replace that amount worn to below *required limit.*

It is stated that the survey will be completed at the 1st convenient

opportunity. The year of grace expired 4.15.

It is submitted for the consideration of the Committee whether action  
might be deferred.

*M. Ladd*  
*6.4.15*

To complete the survey the vessel requires to be examined in Dry  
Dock.

*M. Ladd*

Mike will write re  
locking P.W. 7/15