

The Leith Hull and Hamburg Steam Packet Co. Limited.

James Currie & Co. Managers.

JAMES CURRIE.
ALASTAIR CURRIE.

16 Bernard Street.

Leith 18th August, 1921.

TELEPHONES:

MANAGERS 807 & 808. OFFICE 407 & 408.
VICTORIA DOCK 643 & 644. HULL WHARF 586.
NEWCASTLE & SUNDERLAND WHARF 479.

TELEGRAPHIC ADDRESSES:

LEITH, GRANGEMOUTH, LIVERPOOL CURRIE.
GLASGOW, NEWCASTLE, HULL, SUNDERLAND PACKET.
DUNDEE ALEXANDER.

AGENTS FOR

UNION CASTLE MAIL STEAM SHIP CO., LTD., LONDON.
CUNARD STEAM SHIP CO., LTD., LIVERPOOL.
ANCHOR LINE (HENDERSON BROS.) LTD., GLASGOW.
ANCHOR DONALDSON, LTD., GLASGOW.

When replying please
refer to

M. 5578.

LLOYD'S REGISTER,
LONDON.

REC'D 23 AUG 1921

ANSD 23

The Secretary,
Lloyd's Register of Shipping,
71 Fenchurch Street,
LONDON, E.C.3.

Dear Sir,

S.S. "STETTIN"

We have your favour of 16th inst. reminding us that the Boiler Survey of above steamer is now due. We may state that we had all arrangements made to take the steamer off for overhaul at Leith after discharging her present inward cargo. The "STETTIN" is employed in one of our regular trades and unfortunately the steamer to relieve her sustained damage while leaving port last night and this has rendered it necessary to despatch the "STETTIN" for another voyage or two. You may rely on us having the necessary work put in hand at the earliest possible moment and we have noted to advise you when and at what port we intend to have the work done.

Yours truly,

James Currie & Co.
P. S. M. M. M.



© 2018

Lloyd's Register
Foundation

THE LLOYD'S REGISTER FOUNDATION
LLOYD'S BUILDING, 100 BROADWAY, NEW YORK, N.Y. 10004

Dear Sir,

RE: [Illegible]

A

The Board of Directors
Lloyd's Register
100 Broadway, New York, N.Y. 10004

Dear Sir,

We have your favor of 11th inst. regarding us that the
Boiler Survey of above vessel is not due. We say that we
had all arrangements made to take the vessel off for overhaul at
least after discharging our present inward cargo. The "SYSTEM"
is employed in one of our regular trades and unfortunately the
vessel is being repaired during this leaving port time
right and this is necessary to depart on the "SYSTEM"
for another voyage. The way will be having the repair-
work done at the earliest possible moment and we have
tried to advise you at that time but we have not had time
to do so.

Referred to Mr. S. J. III.

CRP

11/11/11

Wm. H. [Illegible]

