

5 - OCT 1925

s/s "Stettin"

Ham 16522.

The Hamburg Surveyors reported in 9/25 that they found the H.P. cylinder cover broken & that a new cover made of rolled steel plates had been fitted. They recommended permanent repairs to be effected before the end of October 1905.

A letter (& plan of the new cover) has now been received from the Keith Surveyors stating that the cover fitted at Hamburg is satisfactory & the owners desire that it might be accepted as permanent.

The case has been carefully considered, & it is submitted that the new cover fitted at Hamburg be accepted as permanent & the vessel classed & continued without special restrictions.

It is submitted that
this vessel is eligible to
remain as CLASSED.

without special restrictions.

Ans



© 2018

Lloyd's Register
Foundation