

Subj: - To the chart house being repaired at the owner's earliest convenience.

15 MAR 1928

1

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

SS "STETTIN"

Rpt.

Lth

No.

17339

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the nature or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24.5.92.)

Nature of Survey

DAMAGE.

Damage through

Collision + Heavy weather

(Lth 17291)  
(Ham 17858)

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed .....	3						
Removed and faired or repaired .....							
Faired or repaired in place .....	2	2			2		
Other items:-	new chart house fitted and minor repairs effected.						

a bronze anchor of proper weight stowed on board.

It is submitted the vessel is worthy to remain as classed without

record of Survey

as recommended, without special condition

as now, without etc



© 2018

Lloyd's Register  
Foundation