

14 MAR 1929

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Sch. Sc. STETTIN*Rpt. *Lth*No. *17540*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(*The endorsement to contain a succinct summary of any repairs that have been required and to show the extent or nature of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/21.)

Nature of Survey

6th S.S. No. *1* AND DAMAGEDamage through *striking a buoy.*

now repaired as follows:-

(Dun 8634).

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							
Removed and faired or repaired.....							
Faired or repaired in place.....							

Other items:- *A shell plate on front' have renewed.*

The *6th* S.S. No. *1* has also been held and following repairs done due to wear and tear:- *Vessel placed in drydock, bottom coated, repairs to bulkheads, muddes faired, gudgeons rebushed, rust-damaged rivets renewed minor repairs.*

It is submitted the vessel is worthy to remain classed with record of Survey *2. 29* and notation of *S.S. H.C. 1. 29* without condition as recommended.

*A.1.**2. 29 Lth**Without etc.**S.S. Lth H.C. 1. 29*

© 2018

Lloyd's Register
Foundation