

REPORT of SURVEY for REPAIRS, &c.

(Exceeds at London Office, 15/3/83)

No. 537 Survey held at London Date, first Survey 27 Feb 1 Last Survey 6 March 1883
 Reg. Book. Iron S.S. "Charles Howard" Master Atkinson
 Tonnage under Tonnage Deck 876 Built at Sunderland When built 1866 MONTH. 11
 Ditto of Spar Deck, or Awaiting Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage 1304 Owners F. I. Ycett Port belonging to Sunderland
 Crew Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St' mer, cut on Bm. 844 By whom built W. Pile Destined Voyage Black Sea
 If Surveyed Afloat or in Dry Dock Union Dry DK
 Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.

Last Survey, No. 659 Port Port

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

Damage.

Classed S.S. Cl. No. 3-77 Character in Register Book. 90 A 1
S.S. Sld No. 1-81 2. 83
 Society's Load-Line (if assigned) as painted on Ship
 Society's Freeboard (if assigned) as painted on Ship

Seven butts on the port side and eight on the starboard side riveted, and a few rivets in the stem cut out and renewed. The two intermediate pintles of the rudder cut off and replaced by bracket pintles, the upper brace bushed and the side plates of the rudder renewed.

The bottom cleaned, examined and painted

Present Condition of the									
Decks	Good	Treenails	Rivets. where seen	Good	Windlass and Capstan	Good			
Waterways	Do	Breasthooks and Stenson	Not seen		Pumps	Do			
Comings	Do	Transoms, Pointers, and Crutches	Do		Boats 4 No. (1 new)	Do			
Upper Deck Beams & Fastenings	Not seen	Timbers of the Frame at the openings	Do		Masts, Yards, &c.	Do			
Lower Deck Beams & Fastenings	Do	Ditto at other places	Do		Condition, how ascertained	from deck			
Planksheers		Keelsons	Do		Sails	Good			
Sheerstrakes	Good	Clamps and Shells	Do		Anchors No. of 3 B. 15-2 K				
Topsides	Do	Ceiling	Do		Cables	Not seen			
Wales		Rudder	Good		Hawsers and Warps 5 No.	Good			
Plank (Bottom) and Counter	Do	Copper (or Y.M.) When put on			Standing & Running Rigging	Good			
Engine Room Skylights	Good	(State if on Felt.)			Cargo and Main Hatchways	Good			
Coal Bunker, Openings, Lids, &c.	Good	Cement (if Iron Ship)	1866		Hatches	Good			
General Observations, Opinion as to Class, &c.		Caulking of Bottom, Deck, & Waterways	Good						

She is now in good condition and eligible to remain as classed.

The Amount of Entry Fee ... £ 1 : 1 : 0 received by me, J. F. E.
 19/3/83 Special ... £ 1 : 1 : 0 } 2.4 1883

Certificate (if required) to be sent as per margin... £ 5 : 0 : 0

John H. Heck
 Will C. Davey
 Surveyor to Lloyd's Register of British and Foreign Shipping.

Tuesday, 20th March, 1883.

Committee's Minute
 er assigned
B.S. 3, 83 90 A 1