

(Received at London Office)

Tests of 9 Steel Plates manufactured by Messrs D. Colville & Sons of Motherwell
for Boiler No. R. 2 to be constructed by Messrs Central Marine Eng. Co. of West Hartlepool
for the S.S. "Charles Howard"

No. of visits

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to _____ sample~~s~~ as set forth below, and the temper and bending tests as required by Circular N^o 438.

D.F.
10/10/85

Expenses £ : :

£ : :

To be paid by

Surveyor, Lloyd's Register.

Class out
7.10.88