

19 Mar. 86.

Thomas Phillips

Captain S. Brown, on behalf
of the Owner, Mr. A. Smart of
great St. Helens, London E.C., survey the
Iron Screw Steamer "Charles Howard" of
Sunderland 844 Tons Register, W. Atkinson
Master, while lying in Messrs W. Gray & Co.
Dry Dock at this Port, where she had
been placed, in order to ascertain the
extent of the damage, stated to have
been sustained by grounding on the
Sands in the River Thames, on the 29th
while on a voyage from Taganrog to
London.

For further particulars as to the cause of
the damage, see the Log Book & Protest

On the 7th November 1885 found on
examination, that, with the exception of
the paint being scoured off in places
that the hull had not been damaged.
Recommended, the bottom be cleaned &
painted, in order to place the vessel
in the same condition, as before
with the accident.

Fee One Guinea
£1-1-0.

Thos Phillips