

178
66
LLOYD'S REGISTER OF BRITISH & FOREIGN SHIPPING

Marseilles the 23rd Dec 1889

The Secretary
Lloyds Register

Sir

In answer to yours of
the 17th inst regarding the stern
bush of the S/S Charles Howard, I beg
to inform you that the shaft has drop-
ped a quarter of an inch

I am

Sir

Your Obedient Servant
Francis Westerman

Surveyor to
Lloyds Register

For the Chief Engineer Surveyor's remarks

28/12/89

The tail shaft in this vessel being now a quarter of an inch slack in the lignum vitae; it is submitted that the lignum vitae should be renewed when the Owners next dry-dock the vessel.

A.L.D.

31.12.89

28/12/89

A.S.

24.12.89

C.S.

LLOYD'S REGISTRY
LONDON

REC'D 27 DEC. 89

ANSR

note

28/12

W. Weckerman

Re Shaft of C.S.

"Chas Howard"