

30062

Composite Ship -
REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 103 Survey held at London Date Oct 19th 1868
 on the Ship "Leander" Master E. Petherick
 Tonnage 883 built at Glasgow When built 1867
 By whom built Lawrie Owners Merchant Shipping Comp^y
 Port belonging to London Destined Voyage China
 If Surveyed Afloat or in Dry Dock Canal Dry Dock & East India Dock -

Last Survey, No. 20707 Port London Classed 16 A 1
 11, 64

REPAIRS

Now done, her upper deck partially Caulked, and fittings fitted between the frames under the Forecastle to prevent leakage, and the Gunwaming Straps for the bowsprit renewed.

Present Condition of the

Decks Part Caulked

Waterways } Good

Comings } Good

Upper Deck Beams & Fastenings } firm

Lower Deck Beams & Fastenings } firm

Planksheers }

Sheerstrakes }

Topsides }

Wales }

Plank (Bottom) and Counter

Trunnels Bolts

Breasthooks and Stenson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shells

Ceiling

Budder Yellow Metal

Copper

When put on 1867

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained by examination of the deck

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

She is in good and efficient Condition, fit in my opinion to remain as classed 16 A 1.

P. W. Waymouth

The Amount of Fee.....£..... is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 24th April 1869

Character assigned 16 A 1 WRS