

Chief Surveyors 11. 5. 92

Received from Chief Surveyors

VESSEL'S NAME *Thermopylae* Report *lies* No. 2

For the remarks of the CHIEF SURVEYOR and CHIEF ENGINEER SURVEYOR.

S.S. No.

due

B.S. due

The bottom of this vessel was caulked and re-installed in April '87 under Mr. Duvoy's inspection in London when the vessel was surveyed for Continuation. Again in May '90 the caulking of the bottom was examined at Rotterdam by Mr. Loos and found in good condition, before the metal sheathing was put on. Under these circumstances it cannot be understood how the caulking can be in the condition reported by Mr. Clarke.

It is submitted that Mr. Loos should be requested to offer any remarks he may have to make, for the consideration of the Committee, on the statements in this report regarding the condition of the caulking of the topsides and bottom, and the Victoria Report should be sent to him for that purpose.

*J.B.M.**J.B.M.**J.B.*

12. 5. 92.



© 2018

Lloyd's Register
Foundation