

S. L. Pedersen

It is observed that in the
sketch forwarded with the report on this
vessel the Reamend frames are stated to be
 $3\frac{1}{2} \times 3 \times 8\frac{1}{8}$ which is the size required by the
Committee on submitting the sketch, but
in the Report they are stated to be $3\frac{1}{4} \times 3 \times 7\frac{1}{8}$.
Mr. Fardie should explain this discrepancy
and also state whether any particular
bolt-heads are fitted between shells, as
was done in the vessel No 289.

J. W.

8/11/23



© 2018

Lloyd's Register
Foundation