

ANNUAL SURVEYS.

24965

No. in Reg. Book. on the *Iron S.S. "Adriatic"* Survey held at *Philadelphia* Date, first Survey *October 22* Last Survey *October 23* 1879 Master *W. H. H. H.*

Tonnage *2839* Built at *Newcastle* When built *1873* — *1873*

By whom built *Palmer & Co* Owners *Belgian & American S. S. Co.*

Port belonging to *Antwerp* Destined Voyage *Antwerp*

If Surveyed Afloat or in Dry Dock *In Dry Dock of Wm. Cramp & Sons*

Last Survey, No. *2088* Port of *Troy* Character in Register Book *Classed 3.3. No. 1. 78 5.78*

Condition of the *Good* Treenails *Good*

Terays *do* Breasthooks and Stems *Good*

Rings *do* Transoms, Pointers, and Crutches *do*

er Deck Beams & Fastenings *do* Timbers of the Frame at the Openings *do*

er Deck Beams & Fastenings *do* Ditto ditto at other places *do*

Shoers *do* Keelsons *Good*

Strakes *do* Clamps and Shells *do*

Sides *do* Ceiling *do*

es *do* Rudder *do*

k (Bottom) and Counter *do* Copper or Y.M. When put on *do*

ne Room Skylights *Good* Coal Bunker, Openings, Lids, &c. *Good* Scuppers *Good* Cargo and Main Hatchways *Good* Hatches *Good*

ral Observations, Opinion as to Class, &c. *This vessel was placed in the Dry Dock for the purpose of examining the bottom, stern, keel and propellers, and they were found in good condition. It was found that a small chink appeared on the upper and lower edge of stern post, this has been strengthened by two steel castings, fitted on each side of the lower part of stern post and securely riveted. This vessel is now in a good and efficient state of repair, and in opinion merits the favorable consideration of the Committee to be continued. 100 A 1.*

Committee's Minute *11th November, 1879.*

Character assigned *100 A 1.*

Wm. H. H. H.

Surveyor to Lloyd's Register of British and Foreign Shipping

Certificate (if required)

Foundation