

Received by Chief Surveyor

8.8.98

Received from Chief Surveyor

VESSEL'S NAME Inds. Nederland

Report Aut No. 3776

The remarks of the Chief Surveyor are desired on this case for the consideration of the Clas sing Committee.

"The endorsement to contain a precise summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Clas sing Committee may have all the salient points presented in the endorsement." Extract from Sub-Committee's Report 26/9/91.)

Nature of Survey

2<sup>nd</sup> S.S. No.3 further assures

The S.S. 2nd No.3 due 10.96 was held at Antwerp in February and July 1897, to complete which the tank top under the boilers required to be repaired, and the Owners stated that this repair would be effected by degrees.

Several of the plates were renewed in June last, and the remainder — proposed to be done on the vessel's return.

The Antwerp Surveyors now report the bottom has been examined in dry dock, and some minor repairs effected. Sixteen tank top plates have — been renewed, and it is proposed to renew the remainder (about twelve in number) and test the tank on the vessel's return, which the Surveyor recommends for approval.

The year of grace expired at the end of October last.

This proposal is submitted for the favourable consideration of the Committee, and in the meantime the vessel might be allowed to remain as classed, record of survey and notation of S.S. 2nd. No.3 being deferred until completion of repairs, as recommended.

S.A.N.  
Oct 18/8/98



© 2018

Lloyd's Register  
Foundation