

Received by Chief Surveyor _____

Received from Chief Surveyor _____

VESSEL'S NAME *S.S. Nederland* Report *Ant* No. *3875*

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the causes or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 21/5/91.

Nature of Survey

COMPLETION OF S.S. No. *3*

The S.S. No. *3* partly held at *Antwerp 2/97. 7/97 8/98*
now completed, and the following repairs done (due to *wear & tear*) :-
9 new plates fitted on tank top under boilers.

Several of these plates have only been fastened with bolts. It is intended to rivet same & test the tank on return from present voyage, as it is intended to use the tank for water ballast

The plating was drilled with satisfactory results. (See Ant. Rep 3451. 7/97)

It is submitted the vessel is worthy to remain classed *100 A1*with record of Survey *10/98* and notation of S.S. *Ant*

2nd N° 3.7/97 as recommended. *subject of the tank being rivetted & tested previous to its being used for water ballast as proposed.*

*100 A1**10/98 Ant.**S.S. Ant 2nd N° 3.7/97**} subject etc.*

© 2018

Lloyd's Register
Foundation