

Slkg 843

Strathleven

11.6.90

Vessel stranded. The bottom plating
under the Engines & Boilers is up about
1½ ins in either side of ship for a length
of twenty ft. This should be surveyed &
reported upon on vessel's arrival at a home
port



© 2018

Lloyd's Register
Foundation