

18-1-1935
 18-1-1935
 JAN 1935

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Tw. Sc. "ARANDORA STAR" Rpt. _____ Sou _____ No. 15653**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____

The Southampton Surveyors report this ship placed in dry dock, the bottom cleaned and coated and the requirements of the 1st S.S. No.2, due 5,35, partly complied with.

Alterations have been effected to ^{the} Swimming Bath, some new public rooms constructed, a new oil fuel bunker fitted (the pumping arrangements to same are not yet complete and bunker will not be used until these are in order) and other minor alterations carried out, all in accordance with approved plans.

It is submitted the ship appears worthy to remain as classed with record of survey 12,34.

100A1
 with freeboard
 12,34 Sou
 Fitted for oil fuel etc.

To complete the survey: see report



2018
 Lloyd's Register
 Foundation