

Port of _____

19

REPORT ON MASTS, SPARS, AND RIGGING.

Dear Sirs

Having, in accordance with your instructions,
 examined the Masts, Spars, Iron Work of same, and Rigging, of the
 (Name of Vessel) SS Arandora Star

on the (Date of examination) 22/11/38 1938,

I have to report that I found

Referring to the Fore Rigging in the above report, I understand that owing to the structural alterations in progress, it will be necessary to shorten the rigging about 9 or 10 ft., as this will cut off the wasted ends. I have recommended the shrouds to be cut and refit.

H. D. Pearson

Fee £ : :

To the Surveyors,

Lloyd's Register of Shipping,

Newcastle on Tyne

Repair effected as recommended. ✓



© 2018

Lloyd's Register
Foundation