

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME ARANDORA STAR Report LIV. No. 114289**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____

CONDITION _____

When due _____

Subject to repairs to upper part of rudder being specially examined at next dry docking and to steering engine sole plate being renewed at the first convenient opportunity.

was
17.6.40



© 2018

Lloyd's Register
Foundation