

"MANUNDA"

*Lawson 29411*  
Mel. 44533

fore this case receives consideration,  
veyors should say whether the propeller  
side fastenings were examined at the  
king now reported, and whether the  
n of screwshafts was measured.

*[Signature]* *X 27/11*  
21.11.56.

*See encl on 8.1.57*  
*[Signature]*



© 2018

Lloyd's Register  
Foundation