

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
 { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

24th February, 1965

C
DNS/RW

Dear Sirs,

CLASSING LETTER

14290 "HANSEATIC". As recommended, except that class has been continued subject to oil fuel deep tanks C.11 and 12 (leakage) not being pressed up until repairs are effected.

It is concluded that the port and starboard I.P. turbines were examined at this time, but your confirmation is desired as this is not clear from either the Report or Interim Certificate.

14302 "URUNDI". As recommended.

According to the records in this Office, the following items have not been seen for more than four years and it will be appreciated if you will request the Owners to make the necessary arrangements to have these items surveyed as soon as possible:-

Main engine No. 3 cylinder, piston, cover, valves and gear.

Nos. 3 and 6 top ends and bearings.

No. 1 bottom end and bearing.

Nos. 2, 3, 4 and 6 main journals and bearings.

Crankcase relief devices.

Starboard bilge pump.

Main salt water cooling pump.

Aft main lubricating oil pump.

Upper fresh water cooler.

Inboard lubricating oil cooler.



© 2018

Lloyd's Register
/cont...
Foundation

- Page 2 -

Aft main air receiver.
Port outboard auxiliary engine.
Main fresh water cooling pump.

Yours faithfully,

pro Clerk to the
Classification Committee

The Surveyors,
HAMBURG



© 2018

Lloyd's Register
Foundation