

30 May 1961

NAME "ORIENTAL QUEEN" REPORT YKA. No 3815

EA

Existing Conditions of Class: SUBJECT to repairs to forward tunnel side tank (s.s.) being tested, and to set in shell plates J.6 & 7, K.6 & 7 (s.s. from fwd) being specially examined and dealt with as necessary, by the next drydocking.

Appendix. (As before ~~or None~~)

is due: C.S.H. (D) case - due date 9,64.

of Present Survey: (Afloat and in dry dock)

Docking:- Advancement of Special Survey.

Testing repairs - part deferred items as above.

Alterations - 2 new deep tanks fitted etc.

al Features:

Perim Certificate in order (Yes-No-None)

Outstanding: ~~XX (If any for S.S.)~~

FOR PORTION OF SURVEY HELD:-

See List in Ship Reports Dept.

to be completed by:

Recommendation:

SUBMITTED record of DS 8,61 be assigned, subject to set in shell plates J.6 & 7, K.6 & 7 (s.s. from fwd) being specially examined and dealt with as necessary next drydocking, without other conditions.

DS 8,61 Subject
Without.

S.R.L. APPENDIX (AMENDED)

Shell plate in 1st strake below sheerstrake between frs. 39/40 (p.s) slightly indented.

After centreline sheerstrake plate indented. (C.S.H.).

Special Survey due 9,64 to be (D) Survey.

FREEBOARD SURVEYORS TO NOTE.

IT IS FURTHER SUBMITTED the Surveyors be requested to advise if by "deep tanks in No.4 hold" they mean the new F.W. deep tank now fitted or ~~the~~ the existing tunnel side tanks.

CSSS. Records Dept.
to no. 3815
RECORDS
DEPT.

ad. 21.12.61

5/1/62