

4E

30 NOV 1961

subject to

by Chief Engineer Surveyor


Received from Chief Engineer Surveyor

NAME "ORIENTAL QUEEN" REPORT YOKOHAMA No. 3815

TS p due 8/62 S due 8/61 now held.

D.B.S. due 9/61 now held.

C.S. advanced.



Surveyor reports some repairs to port screwshaft liner
in way of sterntube gland.

Furthermore, a number of alterations were made ^{to} piping
arrangements in accordance with approved plans and rule requirements.

It is submitted that this

vessel is eligible for THE

RECORDS D.B.S. 8/61, T.S (CL) P+S 8/61.

S.R.L. appendix note

Port screwshaft liner ~~repaired by~~ ^{blazed} ~~blazing~~ in way of
stern gland. Remd 19/62.

Std. 30.11.61.