

COPY

Ship's name "ARISTON" Port Cpn. No. 20385

The class is subject to indented shell plates A.4 & 5, B.4 (p.s. from fwd) being specially examined and dealt with as necessary next drydocking.

The COPENHAGEN Surveyors report (3,63), ship examined afloat for damage stated caused by fire and ship found to be extensively damaged.

The Surveyors further report that it has been decided by the Owners and the Underwriters that the ship be sold for breaking up purposes.

In view of the above IT IS SUBMITTED
no ACTION need be taken meantime
pending receipt of further information
as to the ship's ultimate disposal.

SPL
11.7.63.

C.S.S. Records Dept.
to note.