

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report Jan^y 16th 1893 When handed in at Local Office is Port of London 18 JAN 1893

No. in Reg. Book 546 Survey held at London Date, First Survey Dec^r 7th 1892 Last Survey Jan^y 12th 1893

on the ~~Wood~~ Iron ~~Sc. Sr.~~ Silvertown Master D. Merton

TONNAGE:-
GROSS 4935 Built at Newcastle By whom C. Mitchell & Co. When 1873
UNDER DEK 4913 Owners Ind. Adv. Sul. Por. & Telopl. Wks Co. Ltd Port belonging to London
NET 3774 Owners' Address
(If not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock Thames L^d Destined Voyage West Coast S. America

WB=DbA tons; f tons; uE&B tons; CellDB tons; }
FPT tons; APT tons; MT tons. }
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey, No. 52712 Port Lon
CHARACTER: * for Special Survey, Date of last Survey and of Periodical Surveys. 100 A. 1
Machinery and Boiler Surveys (including date of N.B., if any). N.B. 80
pt. Shade dk with freebid Z.M.C. 6.91.
S.S. Ton. N. 3-6.86
S.S. Ton. N. 1.90
2.92.
Society's Freeboard (if assigned) as painted on Ship and now verified } 8 ft. 10 1/2 ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

This vessel was placed in the Thames Iron Works Dry Dock the bottom examined, found in good order cleaned and re-coated. 24 slack rivets in the lower part of the propeller post taken out and renewed.

The vessel was found to be deficient of one bower anchor this has now been replaced, the following being the particulars of test certificate. - N^o 22865.

Anchor wt^t 45.1.14 Test 39.9.2.21 Sunderland P.H. N^o 20th 1891.
Rule 4 1/2 C. 36 16/20 Tons. Sg^r J. Hartness.

SUMMARY OF DAMAGE REPAIRS: - Plates, Paired or Repaired; Frames, ditto. Plates, Renewed; Frames, ditto. Other Repairs

PRESENT CONDITION OF THE		Parts		Copper, or Y.M.		Hatches	
Decks	<u>Good</u>	Transoms, Routers, & Cautokes	<u>Parts</u>	(State if on Felt.)	<u>✓</u>	Hatches	<u>Good</u>
Waterways	<u>"</u>	Timbers of Frame at the openings	<u>seen</u>	When put on, Month	<u>✓</u> Year	Boats	<u>"</u>
Coamings	<u>"</u>	Ditto ditto at other places	<u>seen</u>	Rudder	<u>Good</u>	Masts, Yards, &c.	<u>"</u>
Up'r Dk. Beams & Fastenings	<u>Parts seen</u>	Keelsons	<u>Good</u>	Windlass & Capstan	<u>✓</u>	Condition, how ascertained	<u>From Hk</u>
Low'r Dk. Beams & Fastenings	<u>Good</u>	Clamps, Shells & Stringers	<u>Good</u>	Pumps	<u>"</u>	Sails	<u>Stated Good</u>
Plating	<u>Good</u>	Salting (State if examined.)	<u>Good</u>	Engine Room Skylights	<u>"</u>	Equipment letter	<u>✓</u>
Planking	<u>✓</u>	Ceiling	<u>Good</u>	Coal Bunker, Open'gs, Lids, &c.	<u>"</u>	Anchors, No. of	<u>4 B 15. 2 H</u>
Excesses or Rivets	<u>Parts seen</u>	Cement or Asphalt (State which.)	<u>Not seen</u>	Scuppers	<u>✓</u>	Cables (State if now ranged)	<u>No</u>
Breasthooks & Stem	<u>Good</u>	Tanks (State if now tested.)	<u>do</u>	Cargo & Main H'tch'ys	<u>"</u>	" length	<u>Stated Complete</u>
		Caulking of Bot'm, D'k, & Wat'r'ys	<u>✓</u>			" Rule length	<u>✓</u> size <u>"</u>
						Hawsers & Warps	<u>Good</u>
						Standing & Running Rigging	<u>"</u>

General Observations, Opinion as to Class, Recommendation, &c. :-

The vessel so far as seen is in good and efficient condition and eligible in my opinion to remain as classed and to have record of survey 1.93.

Office Fee (if chargeable) per Sec^o II, Sec. 27 £ : : Fees applied for, : :
Survey Fee (per Section 28) £ : : 18.
Special Damage or Repair Fee (if any) (per Sec. 28.) £ : :
Travelling Expenses (if chargeable) £ : : Received by me, : :
Second Surveyor's Fee (if any) £ : : 18.
*Is Certificate now required? ✓

Committee's Minute
Character assigned 891.93 100A1 pt. Shade dk. with freebid.

FRID 20 JAN 1893
R. T. Johnson
Surveyor to Lloyd's Register of British & Foreign Shipping.

Form No. 2 for Repairs. - 305. - L.R.F.B. - 10,000. - 1892. - Transfer Ink. (The Surveyors are requested not to write on or below the space for Committee's Minute.)