

SAT 10 JUL 1897

No. 58914

~~REPORT of SURVEY for REPAIRS, &c.~~

Writing Report 9 July 1897 When handed in at Local Office

Port of London

Survey held at London

Date, First Survey 6 July Last Survey 7 July 1897

on the Wood, Iron or Steel S.S. "Silvertown" No. of Visits

Master Mr. L. T. M. M. L. T. M. L. T. M.

TONNAGE:-

ROSS 4955

Built at Newcastle By whom C. Mitchell & Co. When 1873 3

UNDER DR. 4913

Owners J. R. G. P. & T. A. C. (including Port belonging to London)

ST 3724

Owners' Address

(If not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Name of Dock Albert Dock Destined Voyage Calais to load

B=CellDBorDBa feet; uE&B feet; f feet; f feet; f feet; f feet; f tons. FPT tons; APT tons; MT feet tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, ribs, and of the inner bottom plating, especially in the boiler space.

CHARACTER
For Special Survey
Date of last Survey and of Periodical Surveys
Machinery and Boiler Surveys
(including date of N.B., if any).

Last Survey, No. 58914 Port London

+100 A. 1. - 1. 97 +100 A. 1. - 1. 97 +100 A. 1. - 1. 97

at Shear dock with freeboard 5.5. hon. h: 3 - 6 86. Sub 2.95

5.5. hon. h: 2 - 95. Bd. 3.95

Society's Freeboard (if assigned) as painted on Ship and now verified

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage through striking dock wall.
One plate in 6th stoke below sheer tone in 7th stoke found indented on the Starboard side in W. 1 hold and the latter plate fractured; two frames in way of same each in one of them fractured.Temporary repairs now done for the voyage to lay a cable between France & America:— a doubling plate fitted to the 7th stoke below sheerstake in way of the fracture & a doubling plate fitted to the fractured frame. The rivets in the landing edge in way of indent renewed.

Permanent repairs will be done on the vessel's return

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Repaired ...								
Faired or Repaired ...								

PRESENT CONDITION OF THE	Timbers of Frame at the openings	Rudder	Hatches
Decks	Ditto ditto at other places	Windlass & Capstan	Boats
Waterways	Keelsons	Have Pumps now been examined and found efficient?	Masts, Yards, &c.
Coamings	Stringers, Clamps & Shelves	Have Sluice Valves now been examined and found efficient?	Condition, how ascertained.
Up'r Dk. Beams & Fastenings	Salting (State if examined.)	Have Watertight Doors now been examined and found efficient?	(State if wedges removed)
Low'r Dk. Beams & Fastenings	Ceiling	Have Watertight Plates under Sounding Pipes	Sails
Plating	Cement or Asphalt (State which.)	Engine Room Skylights	Equipment letter X
Planking	Tanks (State if now tested.)	Coal Bunker, Open'gs, Lids, &c.	Anchors, No. of
Rivets or Treenails	Caulking of Bot'm, Dk, & Wat'r'y's	Scuppers	Cables (State if now ranged.)
Breasthooks & Stemson	Copper, or T.M. (State if on Felt.)	Cargo & Main H'tch'w'ys	" length (on board) size
Transoms, Pointers, & Crutches	When put on, Month Year		" Rule length (per Table 22) size

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.97," or "to remain as classed and to have record of survey, 1.97, and the notations of No. 1.97 and ptND97, &c."

This vessel, so far as seen, is eligible in my opinion to remain as classed for the voyage without fresh record of survey.

Office Fee (if chargeable) per Scale II, Sec. 27 2

Survey Fee (per Section 28) 2

Special Damage or Repair Fee (if any) 2

Travelling Expenses (if chargeable) 1.00 10%

Second Surveyor's Fee (if any) 2

Fees applied for,

12/7/97

Received by me,

30/7/97

A/C

FRI. 5 JAN 1900

Committee's Minute

TUES 13 JUL 1897

TUES. 12 JUL 1898

FRI. 8 JUN 1900

Character assigned Deferred for repairs in port note for L.

Deferred

White Star Line Note for L.

White Star Line Note for L.