

# 11959

## Report of Survey for Repairs, &c., of Engines and Boilers.

No. 11959	Date of Writing Report	23 <sup>rd</sup> Dec <sup>th</sup>	is 92 Port of	Glasgow	(Received at London Office.)
No. in Reg. Book	Survey held at	Glasgow, City of Agra.			Date first Survey
577	on the Machinery of the				Last Survey 21 <sup>st</sup> December 1892
Tonnage	Gross 3274	Vessel built at	Glasgow	Master W. M. Green	No. of Visits 1
	Net 2133	Engines made at	Glasgow	By whom C. Connell May	YEAR. 1879
Registered Horse Power	376	Owners G. Smith & Sons	When 1891	When 1879 - 5	MONTH. 5
No. of Main Boilers Two	Steam Pressure - in Main Boilers 160 lbs	Surveyed Afloat or in Dry Dock Govan	Boilers, when made (Main) 1891 (Donkey) 1891		
in Donkey Boiler		(State name of Dock.)	Voyage Indian		
Last Survey No. Port			Class of Vessel & Machinery X 100A1		
(State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.)			(As in Register Book, including dates of Special Surveys of Ship and of last Boiler Survey)		
Repairs due to other causes. State also the dates and initials of any letters respecting this case.			S.S. No. 3 - 6.91 + N.E.B. 691 + L.M.C. 691		
Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?			No		
Do.	"	Donkey "	"	"	No
If this was not done, state for what reasons?			No survey due		
And what parts of the Boilers could not be thus thoroughly examined?			No		
Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?			No		
Did the Surveyor examine the Safety Valves of the Main Boiler?			No		
At what pressure were they afterwards adjusted under steam?			No		
Did the Surveyor examine the Safety Valves of Donkey Boiler?			No		
To what pressure were they afterwards adjusted?			No		

When this vessel was in dry dock, the sea-cocks were overhauled and examined, the propeller and fastenings were examined externally, and found in good order.

Insert Character of Ship and Machinery precisely as in the Register Book.

**General Observations, Opinion, and Recommendation:** — As far as seen, this vessel's machinery is in safe working condition, and eligible in my opinion to remain as classed, without fresh record of survey.

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey; thus, for example, B.S. 1.91, B.C.M.S. 1.91, or X.L.M.C. 1.91, as the case may be.)

Office or Registration Fee (per Sec. 27)	£	;	Fees applied for
Survey Fee (per Section 28)	£	/	18
Special Damage Fee (per Section 28)	£	/	
Travelling Expenses (if chargeable)	£	/	18

\*State if Certificate is required.

Committee's Minute

FE 30 DEC 1892

Assigned

As now

R. J. Bellenden  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Glasgow

*It is submitted that  
this vessel is eligible to  
remain A.S. CLASSED.*

1195780

If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or cause it to show through to the other side.

*D.W.L.*

28.12.92