

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 29th Apr 1893 When handed in at Local Office

Port of London

No. in
Reg. Book.

Survey held at

Vilbury

Date, First Survey

28th April

Last Survey

29th April

1893

286 on the Wood Iron and Steel

S.S. Glenfruin

Master - E. Norman 80-83

TONNAGE:-

GROSS 2981

UNDER DECK 2696

NET 1892

Built at Glasgow

By whom

Lon. & Glas. C. (Linn) When 1880 11

Owners M. & Gregor Gow & Co.

Port belonging to Glasgow

Owners' Address

(If not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Afloat Name of Dock Vilbury

Destined Voyage Middleboro. via Bremen

WB=DBu tons; f tons; u&B tons; Cell DB tons; FPT tons; JPT tons; MT tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey, No. 53785 Port Lon

CHARACTER * for Special Survey Date of last Survey and of Periodical Surveys	Years Assigned Period Interval	Machinery and Boiler Survey (including date of N.P., if any)
100 A1 10.92		+LMC 10.91 +NB 10.91

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Special Survey N° 3 (Part)

Now done, - N° 3 hold, side bunkers (upper & lower), and engine and boiler space cleared, ceiling removed as per Rule, the internal parts of the vessel in these spaces have recently been sealed and re-coated, and are now in good condition. N° 3 water ballast tank (which is in N° 3 hold and engine and boiler space) was tested by water pressure, as required by Rules, and found tight.

The owners' representative proposes to continue this Survey at Middleboro. for which Port the vessel leaves tomorrow via Bremen.

To complete the S.S. N° 3. The whole of the Rule requirements have yet to be complied with, excepting the examination of the N° 3 hold, side bunkers, ~~part~~ engine and boiler space, and testing of N° 3 water ballast tank. Owners advised respecting this. It was not considered necessary to drill the shell plating in this case.

SUMMARY OF DAMAGE REPAIRS: - Plates, Faired or Repaired: - Frames, ditto. - Plates, Renewed: - Frames, ditto. Other Repairs: -

PRESENT CONDITION OF THE

Decks	Good	Transoms, Pointers, & Gratches	Good	Copper, or Y.M.	✓	Hatches	Good
Waterways	"	Runners of Frame at the openings	"	(State if on Felt.)		Boats	"
Coamings	"	Ditto ditto at other places	"	When put on, Month	✓ Year	Masts, Yards, &c.	"
Up'r Dk. Beams & Fastenings	"	Keelsons	"	Rudder	Part seen, Good	Condition, how ascertained	From deck
Low'r Dk. Beams & Fastenings	"	Clamps, Shells & Stringers	"	Windlass & Capstan	"	Sails	Stated to be good
Plating	"	Salting	✓	Pumps	"	Equipment letter	W
Planing	"	(State if examined.)	"	Engine Room Skylights	"	Anchors, No. of	3 B. 1 S. 2 K.
Blanking	"	Ceiling	"	Coal Bunker, Open'gs, Lids, &c.	"	Cables (State if now ranged)	No
Reinforcing or Rivets	"	Cement or Asphalt	"	Scuppers	"	" length	Stated to be
Breasthooks & Steamers	"	(State which.)	"	Cargo & Main H'tch'ys	"	" Rule length	Complete
		Tanks N° 3 externally	✓			Hawsers & Warps	Good
		(State if now tested.)	"			Standing & Running Rigging	"
		Caulking of Bot'm, D'k, & Wat'rs'ys	"				

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: - "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."

This vessel as far as seen is in good and efficient condition and eligible in my opinion to remain as classed without fresh record of Survey & the notation of S.S. N° 3 to be deferred till the completion of same

Office Fee (if chargeable) per Scale II., Sec. 27	2	Fees applied for,	
Survey Fee (per Section 28)	204	Completion	18
Special Damage or Repair Fee (if any)	2	Received by me,	
Travelling Expenses (if chargeable)	2		18
Second Surveyor's Fee (if any)	2		

*Is Certificate now required?

Committee's Minute

TUES. 2 MAY 1893

TUES. 13 JUN 1893

FR 7 JUL 1893
TUES. 11 JUL 1893
FRI 8 DEC 1893
FRI 23 FEB 1894

Character assigned

Deferred for
Write Mdb. Comple
of No. 3
Rpt L Mdb
2/5/93

No. 286 on the Wood Iron and Steel S.S. Glenfruin

Is a Report also sent now on the Machinery of the Ship? If not, state whether, and when, one will be sent?

Form No. 2 for Repairs, &c. (The Surveyors are requested not to write on or alter the space for Committee's Minute.)

p.c. no. 3