

REPORT of SURVEY for REPAIRS.

No. 396 Survey held at London Date Feb 21 1830
 on the Sh. Lady Penelope Master Darison
 Tonnage 584 Built at Cubitta When built 1817
 By whom built _____ Owners T. Ward
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock in Blackets Dock

Original Survey, No. 1642 & 2444 Dated _____ Classed E 1
 Port London

Repairs *At the present time caulked from the Keel to the Gunwale sheathed over Boarded sides felt & capped to the Water*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c. <u>Good</u>
Plank Sheers <u>Good</u>	Counter <u>Good</u>	Sails <u>Good</u>
Waterways <u>Good</u>	Plank & Treenails (Outside to the Water's Edge)	Cables <u>well framed</u>
Hatchway Comings <u>Firm</u>	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, as required by the Instructions,

Appearance of this vessel is firm & free from working no symptoms of decay & in a very efficient state for the safe conveyance of dry & perishable cargo to & from all parts of the World I am of opinion that Class should be raised to E 1

The Amount of Fee £ 3 : 3 : - is received by me, W. M. M. M. M.

Committee Minute 13 March 1830

Character assigned raised to E 1