

REPORT of SURVEY for REPAIRS.

10489

No. 57 Survey held at London Date 29 Nov 1850
 on the Ship Lady Kennaway Master Santry
 Tonnage 584 Built at Calcutta When built 1817
 By whom built _____ Owners Teigne & Smith
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock in Messrs Fletcher's Dock

Last Survey, No. 15406 Port London Classed * A 1
SS 48

REPAIRS

at present yellow metal shipped off the Port
 doubling of bottom Caulked. Kulkennies also
 Caulked and bottom reshathed with yellow
 metal — opened at present for general
 survey and timbers found sound & good

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Ym</u> When put on <u>New</u>	Standing & Running Rigging
Plank (Bottom) and Counter	<u>Nov 1850 on Part</u>	
	<u>wood sheath 9/1845</u>	

General Observations and Opinion,

This Vessel is in efficient Condition and
 in our opinion fit for the safe conveyance

The Amount of Fee.....£ _____ is received by me, of my Perishable

Special..... : :

Certificate (if required) : :

Committee's Minute 20th Dec 1850

Character assigned Fit for Service

Carries to & from all
 parts of the world,
 and may remain
 as Classed

Wm. H. Ritchie
Surveyor