

635

19271

REPORT of SURVEY for REPAIRS.

No. 5 Survey held at London Date 20th July 1854
on the Ship Lady Kennaway Master Young
Tonnage 584 Built at Calcutta When built 1817
By whom built _____ Owners Teigue & Smith
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Mr. J. H. Fitcher Dock

Last Survey, No. 18195 Port London Classed *A. 1
REPAIRS at present docked to inspect the state
of the yellow metal sheathing which
was found smooth & good - New main
piece of rudder fitted -

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion, This vessel is in efficient condition
and fit for the safe conveyance of dry and
perishable cargoes to & from all ports

The Amount of Fee.....£ : : is received by me, of the world and
able to remain
as classed
J. H. Fitcher
Special..... : :
Certificate (if required) : :

Committee's Minute 29th Sept^r 1854
Character assigned A. 1 asterisk