

"ARCHGROVE"

Aberdeen Report No. 24166.

Sternframe Repair

In view of the age of the ship and the imminence of the Special Survey, it is not considered that the special condition regarding the examination of the sternframe should be removed at this time.

J.H.S.
12/7/57.