

Port of New York

June 7th, 1922. REGISTER
NEW YORK

REPORT ON MASTS, SPARS, AND RIGGING.

RECD JUN - 9 1922
ANS'D

Dear Sirs:-

Having, in accordance with your instructions, examined the Masts, Spars, and Rigging, and Iron Work of same, of the
S/S "Philadelphia"

I have to report that I found wire rigging more or less rusty, but after knocking rust off in places found wire in strands all right.

Recommend:- All wire rigging to be cleaned and painted.

N.B. - The Superintendent for the Owners was present and gave instructions to the Superintendent of Messrs Fletcher & Company's repair yard to attend to the matter at once.

Gilbert M Edgett

In L

To the Surveyors,
Lloyd's Register of Shipping.

371

NEW YORK

July 1

NEW YORK
JULY 1 1933

REPORT ON WIRE SPARE AND RIGGING

Having in accordance with your instructions, examined the blocks, spurs, and rigging, and from both of same, of the

I have to report that I found wire spurs and blocks, and also

all wire rigging to be standard and correct.

The arrangement of the blocks and spurs, and the

instructions to the superintendent of work, Robert J. Goggin,

appear to conform to the order of work.

W. MacArthur