

Port of Hamburg13 September 1910

REPORT ON MASTS, SPARS, AND RIGGING.

Sirs

Having, in accordance with your instructions, examined the Masts, Spars, and Rigging, and Iron Work of same, of the 5 Mast-steeple Processors

I have to report that I found Nothing on the Foremast-fore & Main masts. On the Aftermain mast found that the nut of the sling band bolt was slack.

Mainmast nothing

Jigger mast. Mast-ropes goose neck slightly

cut other wire all in order

L. Thiel

See L

To the Surveyors,

Lloyd's Register of British & Foreign Shipping,

Hamburg.



© 2018

Lloyd's Register
Foundation