

14 MAY 1963

Ship's Name SS/XX "IONIA" Gross tons 4737

Is there a rpt. 9? Yes. Port Piraeus Rpt. No. 10198

No. of visits 2 First date 3.4.63 Last date 11.4.63

Interim Cert. issued & copy herewith? Yes. Damage rpt. issued & copy herewith? Yes. Last rpt. (H.Q. only) 9707 P.

Date of completing rpt. 11.4.63 Surveyed at, if different from Port above

Surveyed afloat and/or in D.D. Both Last date of examination in D.D. 3.4.63

Has a Load Line Survey been held? No. Freeboard Marks verified

State which additional Rpt. 8 is attached: (Cont); (PS); (~~DR~~); (~~EQ~~); (~~Rig~~)

Survey fees DS £15. 0. 0 Damage fee £ 5. 0. 0 Expenses £ 1. 6. 0

Stamps 1. 3

S.A. fee

I have surveyed the above ship in accordance with the Rules for Docking & Damage stated to have been sustained when vessel struck bottom in the Corinth Canal (see Rpt. D9707) on the 11th August, 1962.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated. Minor wear and tear repairs effected.

Now done for Damage & Condition of Class SRL No.200.

No apparent damage to bottom shell plating found.

It is therefore submitted that this item be now deleted from the SRL.

I recommend that this ship remain as classed with ~~without~~ fresh record of dry docking DS 4,63. ✓  
without condition regarding grounding.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

WEDNESDAY 12 JUN 1963

Minute

DS 4 63  
TS 4 63 MBS 4 63

Surveyor to Lloyd's Register of Shipping



© 2018

Lloyd's Register Foundation

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

action, taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due



**PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.** The reason for repairs must be stated and repairs on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs and, besides being detailed above, should be noted in the following summary. *State what action has been taken regarding items which are subjects of class or in SRL Appendix, whether outstanding or new.* Any alterations in existing particulars in the Register Book should also be reported above.

SUMMARY OF DAMAGE REPAIRS	SHELL PLATES	FRAMES	DECK PLATES	BEAMS	OTHER ITEMS
Renewed					
Removed and faired or replaced					
Faired or repaired in place					



© 2018

Lloyd's Register  
Foundation

June 2018 1/2



## Rpt. 8 (P.S.) DRY CARGO SHIP

Ship's Name SS/MS "IONIA"

S.S. ( ) Due

Port Piraeus

Rpt. No. 10198

<u>Examined &amp; condition</u>		<u>Examined &amp; condition</u>	
In dry dock from	3.4.63	* Air & sounding pipes	Good (Above deck)
" " " to	4.4.63	Doublers under " "	N.E.
Shell plating	Good.	Steering arrangements (main)	Good.
Sternframe	Good.	" " (aux)	Good.
Rudder	Good.	Windlass	Good.
Was rudder lifted?	No.	Masts & rigging	Good.
Plating, etc. in way of shell openings	Good.	Hand pumps & suction	N.E.
Side scuttles & deadlights	N.E.	W.T. doors	N.E.
Overbd. scuppers & discharges	N.E.	Bulwarks, freeing ports, etc.	Good.
F.P. spaces	N.E.	Summer freeboard as verified	-
Chain locker	N.E.		
A.P. spaces	N.E.		
Engine space	N.E.		
Boiler space	N.E.		
Under E. & B.	N.E.		
Coal bunker	None.		
Tunnel & well	Good.		
Cement, asphalt, etc., on btm. shell	N.E.		
Weather decks	Good.		
* Casings	Good.		
* Deckhouses	Good.		
* Superstructures	Good.		
* Skylights	Good.		
* Companionways	Good.		
* Hatchways	Good.		
* Ventilators	Good.		

Other items:

EQUIPMENT:

	Equipment letter	
	Fee ltr., if diff. from eqpt. ltr.	
	Anchors: No. on board	
Cables {	State if ranged	No.
	Length on board	-
	Mean dias. range from	- to
	Rule length	- Dia.
	Mooring ropes	-

\* These items to include their closing appliances

Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"



Surveyor to Lloyd's Register of Shipping

Lloyd's Register  
Foundation



HOLDS & 'TWEEN DECKS:		Examined & condition	TANKS:	Examined & condition	Tested & condition
No. 1	Hold		F.P. tank		
"	'Tween decks		A.P. tank		
			D.B. tanks & c/dams		
No. 2	Hold				
"	'Tween decks				
No. 3	Hold		O.F. bunkers		
"	'Tween decks				
		N.E.	Settling tanks	N.E.	N.T.
No. 4	Hold				
"	'Tween decks		Deep tanks		
No. 5	Hold				
"	'Tween decks		Side tanks		
No. 6	Hold		Wing tanks		
"	'Tween decks				
			Other tanks:		
	Cargo battens				
	Ceiling, etc.				



© 2018

Lloyd's Register  
Foundation

LR FAF 105-70 2/2