

Lloyd's Register of Shipping,


Exchange Building,

Sprott Road, Ballard Estate,

Bombay, 28th August 1940.



P. SOUTHWELL,
ENGINEER SURVEYOR.



The Secretary,

W o k i n g h a m.

Dear Sir,

Referring to Bombay Report No. 6256 on the s.s. "BRITISH EMPEROR" forwarded by last week's mail, I beg to advise that the oil fuel installation of this vessel was examined and found to be in order.

I regret that this information was omitted from the above Bombay Report No. 6256 on this vessel.

I am, Dear Sir,

Yours faithfully,

[Handwritten signature]

[Handwritten initials]



© 2018

Lloyd's Register
Foundation

Lloyd's Register of Shipping

Exchange Building,
Spinnaker Road, Ballard Estate,

Bombay, 28th August 1940.



The Secretary,

W o r k i n g h a m .

Dear Sir,

Referring to Bombay Report No. 2826 on the s.s. "BRITISH EMPEROR" forwarded by last week's mail, I beg to advise that the oil fuel installation of this vessel was examined and found to be in order. I regret that this information was omitted from the above Bombay Report No. 2826 on this vessel.

I am, Dear Sir,

Yours faithfully,

[Handwritten signatures and initials]
H
No right
proced.

21 OCT 1940

LR-FAF-T86-114

