

s/s. "Lord Byron".

It is submitted the Sunderland Surveyors should be informed that it is concluded a continuous liner is fitted to the screw shaft but as no mention of it is in their report they should state whether this is so.

J.W.D. 2/3/17