

"CONTE ROSSO"

Loeffler Boiler - Feed Water Regulating Valve.

IT IS SUBMITTED the Trieste Surveyors be informed that from enquiries made of the Stettin Surveyor it is found that *the material for* this feed water regulating valve was not tested by him, and, moreover, it was made at a works not recognised by the Society.

In the circumstances, it is considered that the Society cannot undertake any responsibility regarding this steel casting, which should therefore be rejected.

The Stettin Surveyor should be advised and informed that in future cases where steel castings are involved which have not been made at works recognised by the Society, he should not issue any certificate relating to the steel castings without reference to this Office.

W.S.

Lrs 24/2/36

W.D.A.

24.3.36.

S.D.



© 2018

Lloyd's Register
Foundation