

URGENT.

s.s. "CONTE ROSSO".

Loeffler Boiler and Escher Wyss Turbine Installation.

IT IS SUBMITTED the Stettin Surveyor be informed a question has been raised regarding his Certificate dated 22nd February, 1936, relating to one cast steel water regulating valve of 60 mm. diameter.

It appears from the Certificate that the cast steel valve chest was made by a Firm which is not on the approved List and that the material was not tested, and accordingly it is considered that this valve should not have been accepted.

The Surveyor should be asked for his remarks, which he should forward by return of post.

The Trieste Surveyors should be advised that enquiries are being made of the Stettin Surveyor regarding this matter and that they will be communicated with in the course of a few days.

NR
16.3.36. *al*

L. Str
16/3/36



© 2018

Lloyd's Register
Foundation