

LIST OF SPARE GEAR FOR TURBINES ETC.

			NO.OFF.
Gear Wheel Bearing Bushes.	Top Half.		2
" " " "	Bott. "		2
& L.P. 2nd Red ⁿ . Pinion Bearing Bushes.	Top. "		4
" " " "	Bott. "		4
1st Reduction.Pinion Bearing Bushes.	Top. "		2
" " " "	bott. "		2
" " " "	Top. "		2
" " " "	Bott. "		2
Turbine. Bearing Bushes.	Top. "		2
" " " "	Bott. "		2
" " " "	Top. "		2
" " " "	Bott. "	1 without lip 1 with lip.	
" " " "	Top. "		2
" " " "	Bott. "	1 with lip. 1 without lip	
Don Rings for H.P.Glands.	Rectangular	8 complete rings. 24 Segments.	
" " " "	Angle Section.	18 complete rings. 54 segments.	
" " I.P. "	Rectangular	10 complete rings. 40 segments.	
" " L.P. "	Rectangular	8 complete rings. 48 segments.	
Rings for H.P.Glands.			26
" " I.P. "			10
" " L.P. "			8
Condenser Tubes.			100
" " Ferrules.			100
Auxiliary Condenser Tubes.			20
Ring for H.P.Ahead casing escape valve.			
" " I.P. " " " "			



© 2018.

Lloyd's Register
Foundation

NO. OFF.

ring for H.P. Astern Casing Escape Valve.	1
" " L.P. Ahead & Astern Casing Escape Valve.	1
" " Main condenser escape valve.	1
as for Main thrust block.	8
ners " " " "	3
as for H.P. & I.P. Adjusting Block.	12
ners " " " " "	3
as for L.P. Adjusting block.	12
ners " " " "	3
Whorl Valve Discs. for bilge pump valve boxes.	2 sets
Rings for bilge pump suction chests.	1



© 2018
Lloyd's Register
Foundation