

S. S. "ELLWIRON".

The remaining half of the Chain Cable has since been placed on board, this has been tested by the Surveyors of the Bureau Veritas and the Certificate of Test is forwarded.

The tests are fully equal to the requirements of this Society and the Cable has been tested on a testing machine approved by this Society.

It is submitted this Chain Cable might be accepted.

The results of the tensile and elongation tests made by the Bureau Veritas Surveyors from the Steel Anchors are satisfactory, but particulars of the Anchor Tests are still required., and the figure 1 should be withheld until these are received.

Cf.

16.6.19.



© 2020

Lloyd's Register
002013-002023-0168
Foundation

Thickness
for Plate, b'dth & th'kns

Thickness
for Plate, b'dth & th'kns