


TELEPHONE N:º 1871.



Malmö, 31st May 1919.

LLOYD'S REGISTER,
LONDON.

REC'D 12 JUN 1919

The Secretary **ANSD**

LONDON.

Dear Sir,

The enclosed First Entry report No. 73 on the steamer "ELLWIRON" also report No. 74 on the hull of the same vessel have been delayed through the present pressure of work at this port.

I am, Dear Sir,

Yours faithfully,

Гроздены

Four pantin
with angles

74-24.8

44
 $4 \times 4 \times 5$
 $3\frac{1}{2} \times 3\frac{1}{2} \times 3$

. 40 -

40-

-34-

 3×3

✓

10

1871

3 X

Toe Bulb, or Channel	✓	✓	✓	✓	✓	✓
Angles on upper edge	✓	✓	✓	✓	✓	✓
Spacing	23			23		
Bridge Deck, Angle, Bulb Angle, Plate	5 1/2	3	3 1/4	5 1/2	3	3 1/4
Toe Bulb, or Channel	✓	✓	✓	✓	✓	✓
Angles on upper edge	✓	✓	✓	✓	✓	✓

„ Angle on ditto.....
 „ Tie Plates.....
 „ Deck. Material and thickness.....
Forecastle Deck Stringer Plate, b'dth & th'kns
 „ Angle on ditto.....

78 W.

JUN 12 1915

Also for Mr. S. A. Hill to note.

to note.

© 2020

of Sleep per
F.R.
angles, or E
aks
ay of Doub
Frames from

Tonnage	}		
Beam ..			
on Deck		Feet.	Inches.
Rule		235	/