

M. M.
2,023

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex
Telex No.: 24305

Telephone: ROYal 9166

Your ref. WC/IH
Marine Superintendent's Dept.

25th October, 1960.

ssn (S)
H/BS

Dear Sirs,

Steamer "BALLYALTON"

I refer to your letter of the 19th instant addressed to the Society's office at Belfast. The case has been examined and I can confirm that when this ship came under survey at Preston on the 17th April, 1956, there were no conditions of class recorded.

As a result of the survey at Preston, however, temporary repairs were carried out and it was recommended that set up bottom plating and damaged floors, etc., should be permanently repaired on the ship's arrival in the Mersey, Clyde or at Belfast, also that the bottom plating should be specially examined on the occasion of the next drydocking for grounding damage.

Yours faithfully,

c.c. BELFAST

pro Clerk to the
Classification Committee.

Messrs. John Kelly Ltd.,
Station Street,
Queen's Quay,
Belfast, 3.



© 2020

Lloyd's Register
Foundation

007013-001623-0202

Suggeste

Date of