

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor 11 MAY 1956

SHIP'S NAME "ALEXANDER SCOTT" REPORT Mil. No. 8043

Blrs. due 11,55 now held.

and the following repairs carried out (due to wear and tear):-

Docking. Screwshaft seen, and now renewed.

Due to the expenses entailed by recommended repairs to the boilers, the Owners have decided to scrap the vessel.

IT IS SUBMITTED the vessel is eligible to remain as classed,
with RECORD of survey S(N) CL 4,56. as-recommended.

It is further submitted action be deferred pending the receipt of further ~~information~~ *information* as to the vessel's ultimate disposal.



02020
8.5.56.

Lloyd's Register
Foundation



002024-002037-0115