

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME "EMPIRE CONLEA" Rpt. Hul. No. 54511

Notes of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/32)

REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH-
LMC FOR CLASSIFICATION.

This case has previously been dealt with in an endorsement dated 19. 12. 47.

The machinery drawings and pumping arrangements have now been approved. Machinery First Entry reports have been received and are in order.

IT IS SUBMITTED that this vessel's machinery is now eligible for Records LMC 10.47,
CL 9.47.

When hull installation assigned

Subject to the oil fuel installation and pumping arrangements being brought up to Rule requirements, safety valves being fitted to cylinder covers and the governor shaft bevel-wheel being renewed.

Particulars for Register Book:-

Oil Engine 4 S.C.S.A.
4 Cyl. 11" - 16 ⁹/₁₆"
MN 47

[Signature]
22. 1. 48.



© 2020

Lloyd's Register Foundation

002038-002050-0108