

s/o "Montoro".

Grk Apt N^o 16/163.

It is submitted, that the Greenock Surveyors should be requested to state whether 2 main bearing bolts have been placed on board as spare as no mention is made of them in their report.

Lr: -29/12/11

JWR

29/12/11

© 2020

Lloyd's Register
Foundation

002051-002061-0185