

of "Belgaum."

Hul Apr 9 190

It is submitted the Hull Surveyors should be informed that it is concluded the diameter of the L.P. Cylinder is 37" & not 27" as given in their report & they should state whether this is so.

Ln:-17/3/16

J.W.S.

17/3/16

J.F.R.

002062-002070-0074

© 2020

Lloyd's Register
Foundation