

Chief Surveyors 26/4/11.

Received from Chief Surveyors

SHIP'S NAME Stl. S.S. "Edavana" Report Glo No. 30018

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Time of Survey 1<sup>st</sup> Entry When due

+ 100A1 ("Steel") "Shade deck"  
2 Dks (v Stl ws) v Shade deck (Stl-Teak s)  
WB = all DB a 85' v E+B 100' f 151' 748t. F.P.T. 39t. A.P.T. 31t.  
"7BH."  
FK. 5BH. to Upper D<sup>k</sup>, 2BH to 2<sup>nd</sup> DK. cem. Lloyds A+C.P.  
B on shade deck 166'

*RM* *RA*  
26/4/11

