


"IMMO-RAGNAR"

Hfs. 5322

Before this case receives consideration,
the Surveyors should be asked whether the safety
valves of the port boiler have been adjusted during
the course of the present Boiler Survey.

19.9.56.



L to

Chas Hfs Hfs



© 2020

Lloyd's Register
Foundation

002094-002100-0197