

002119-002126-0156

2000.12.19.

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel 22 "T.P. TILLING" Report Liv. No. 80885.

For the CHIEF SHIP SURVEYOR ~~CHIEF ENGINEER SUPERVISOR~~

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey _____

When due _____

● 100 A.1. (steel).

1 Dk. (steel) "Well Dk."

DTf 14' 45t. FPT 14t. APT 39t.

FK. 4 BH. Com. Lloyds A & C.P. Q 87', B 9', F 22'. Machinery. Alf

The Certificate of Classification, to be endorsed "Cargo battens not fitted," and the same notation to be printed in the Register Book.

It is concluded the thickness of Raised Quarter deck, clear of openings, is as required & that the deep brackets in way of No 2 Hatch have been fitted at the frames, as shown on approved detail plan, but the Surveyors should be requested to state if this is so

dw
19/20

in letter 15/9/02
M
ALB
2-7-26

